

re. Plans

Fac. Lib Bldg.  
Comm.

F 1.

Brockway

Needs more reading surface in stacks  
#4 and #5 (From left) - no place to read  
N.Y. Times bound volumes 32" x 23" if tables  
are occupied. (See Nowak comments)

Lectern in stack #3 might be nearer center of  
stack.

✓  
Welter

Stacks on 1st floor (at south end) should give  
easier access to cubicle (east side) - there  
will be traffic problems.

Could short north-south stack  
be replaced by adding 1 section  
to each of short east-west stacks?

Nowak

Questions size of stack lecterns. Are they  
ample for N.Y. Times, for example? What  
about shadow? ✓

Would it be possible to sound-proof carrels  
facing the wall?

MSH

Ditto Nowak and Brockway on lecterns.

What about 10" or 12" shelves for Government  
Documents? - room enough for 12" shelves  
here and consulting table (e.g. cat. consult-  
ing table?)

Ditto Welter remarks about south-east stacks.

Fine if booths could be pleasantly sound-  
proofed.

What about 18' of stack where tables now are -  
(avoid irregular sizes as much as possible)  
Would there still be enough room to get around  
end of stack?

F 2.

Nowak

Regrets absence of sufficient exhibit space.  
Too little in proportion to the rest of the  
Library.

MSH:

Still questions Lobby reading area.

Files really ought to be near reference  
area.

Is there room for 5 catalog cases?

Why 26" x 22" book truck in cataloging  
room? (O.K.O - for unpacking shipments?

Typ. stand in Assistant Librarian's Office? 206

F 3.

Welter

What about facing East carrels - toward the  
East ?

MSH ok

MSH

Question about ledge on East. - Is this  
pipes?